



JESCO RESOURCES, INC.

1437 GENTRY ST. • P.O. BOX 12337 • NORTH KANSAS CITY, MISSOURI 64116
(816) 471-4590 • TELEX 43-4339 • FAX 816-471-2240

RECEIVED

JUN 24 1991

RCOM SECTION

21 June 1991

Mr. Mike Sanderson
Chief, RCRA Branch
U.S. Environmental Protection Agency
Region VII
726 Minnesota Avenue
Kansas City, Kansas 66101

Re: June 14, 1991 RCRA Inspection Violation Notice
(40 CFR 262.11)

Dear Mr. Sanderson:

Pursuant to the referenced notice, Jesco Resources spoke with Sandi McCleod on June 21 to discuss the corrective actions that would be required. As a result of our discussion, the following corrective actions have occurred.

Four (4) waste streams have been defined and samples of these streams have been taken and forwarded to General Testing Laboratory, Kansas City, Missouri, for TCLP analysis. Test results will be forwarded to you as soon as they are received and the materials will be properly disposed of at that time.

Since we do not use or store herbicides or pesticides at our facility, we are informed that we will not need to run that portion of the TCLP analysis (according to Ms. McCleod).

The designated streams and samples are as follows:

<u>STREAM IDENTIFICATION</u>	<u>SAMPLE I.D.</u>
1. Air Scubber Filtration Stream	System Filter
2. Oil Separation Filtration Stream	Oil Filter
3. Oil Dry, Plant Floor Residues	Cumulative Plant Sample
4. Production Leakage and Equipment Cleanout (Miscellaneous oil, asphalt, grease materials)	Cumulative Plant Sample




R00029864
RCRA Records Center

Mr. Mike Sanderson
22 June 1991
Page Two

By this timely reply, we believe we have addressed the citations "corrective action(s)" requirement. However, if further information is required, please contact this office.

Sincerely,

JESCO RESOURCES, INC.

A handwritten signature in black ink, appearing to read 'R. S. Howell', is written over the printed name and title.

Richard S. Howell
President

RSH/bj